RAILROAD TELEMETRY DEVICES OFTEN REPORTED AS "SUSPICIOUS"

Telemetry devices placed on railroad cars have recently been reported to authorities as "suspicious", being mistaken for some type of explosive device.

BP, the company involved with installation of these devices, states that there are approximately 100 railroad cars equipped with these devices. These telemetry devices can be found on both rail tank cars and covered hopper cars.

Should you have any questions regarding these devices, there should be a tag with an 800 number to call.









